ALL.ET

OUT59061

1966 JUL 9 01 42Z

P 090119Z

FM NPIC WASHDC

TO RUCSC/SAC OFFUTT AFB OMAHA NEB

RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA

RUCVAA/2D RTS BARKSDALE AFB LA

RUEKDA/DIA WASHDC

RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD

RUEPIA/CIA WASHDC

RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF

RUWGAA/2 AF BARKSDALE AFB LA

BT

S E C R E T CITE NPIC 7724

15TH AF (FOR DI), SAC (FOR DIM, GOLDEN TREE, DOCR, DM 4) 2D AF (FOR DI).

- 1. CAMERA B 125 WAS USED IN MISSION 8105 FLOWN ON 6 JULY 1966. 11 JUL 1966
 PROCESSING WAS ACCOMPLISHED BY NAVRECONTECHSUPPCEN.
 - 2. ORIGINAL NEGATIVE:
 - A. EXPOSURE WAS ADEQUATE AND RESOLUTION WAS GOOD.
- B. 9R SIDE: EDGE FOG IS PRESENT ALONG BOTH EDGES HEAD TO TAIL POLICY
 ROLLER CHATTER WAS NOTED IN THE FIRST ONE-THIRD OF THE MISSION.

 PLUS DENSITY LINES WERE NOTED IN A RANDOM PATTERN THROUGHOUT THE MISSION.

 TWO FRAMES, 982/983, WERE FOGGED ALONG THE OUTBOARD EDGE OF THE PILM HAD

 IT DID NOT DEGRADE THE IMAGERY. MANUFACTURING SPLICES ARE LOCATED PAGENTALY.

 IN FRAMES 932 AND 1933. A HEAT SPLICE WAS NOTED IN FRAME 1120.

 SPAD
 NSA-LO
- C. 9L SIDE: INTERMITTENT STATIC ALONG THE OUTBOARD EDGE IS

 PRESENT IN FRAMES 1 THROUGH 41 AND ON THE INBOARD EDGE FROM HEAD TO

 Idvance 13

 TAIL. THERE IS A PLUS DENSITY SPOT Ø.6" FROM THE INBOARD EDGE AND

 Sanitzen

 4.65" APART HEAD TO TAIL. TWO ROWS OF MINUS DENSITY DOTS ARE LOCATED

 Ø.25" AND 3.85" FROM THE INBOARD EDGE AND 1.68" APART. THEY ARE

 PRESENT IN THE FRAMES FROM 1 THROUGH 47 AND 1 THROUGH 32, RE
 SPECTIVELY. INTERMITTENT INBOARD EDGE FOG AND OUTBOARD

SINE

ROLLER CHATTER ARE PRESENT THROUGHOUT THE MISSION. THERE

ARE FOG STREAKS ALONG THE OUTBOARD EDGE IN FRAMES 1657 AND 1721.

MANUFACTURING SPLICES ARE LOCATED IN FRAMES 542 AND 1893 AND EACH

WAS ACCOMPANIED BY NORMAL FOG AND HANDLING MARKS. THE FILM WAS

WRINKLED ALONG THE INBOARD EDGE OF FRAME 2145 AND 2149 AND THE OUTBOARD

EDGE OF FRAMES 2150 THROUGH 2156. IT APPEARED AS THOUGH THE

FILM WAS MISTRACKING DURING A WIND UP PROCEDURE. HEAT SPLICES WERE

NOTED BETWEEN FRAMES 967/968 AND IN FRAME 1078.

- D. BOTH SIDES: SOME STREAKED FRAMES WERE NOTED ON BOTH SIDES. THIS WAS PROBABLY DUE TO VEHICLE MANEUVERS. THE VERTICAL INDICATOR DOT WAS BLOOMED. THE LAST TITLED FRAME IS 2169.
 - E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.
 - 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY WEATHER.
 - B. PRINTING AND PROCESSING WAS GOOD.
- C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 15 PERCENT OF THE MISSION.

GP-1

SECRET

END OF MESSAGE